## decimal eRT Keyboard & Mouse Controls

The following document details the shortcut keys provided in the user interface of the decimal eRT app. The shortcuts are detailed in their appropriate section of use.

## **Mouse Controls**

Display Views	
Key	Description
Double Left Click	Reset Zoom (fit to scene display)
Right Click + Drag Up	Zoom in
Right Click + Drag Down	Zoom out
Middle Click + Drag	Pan
Left Click + Drag	Rotate (3D only)

## **Keyboard Controls**

General		
Key	Description	
[	Toggle expansion of left side task menu	
]	Toggle expansion of right side task menu	
Ctrl + =	Increase font size	
Ctrl + +	Increase font size	
Ctrl + -	Decrease font size	
Ctrl + 0	Reset font size to default	
F5	Manual Forced refresh of application and data	
F11	Toggle full screen view	
3D Views		
Key	Description	
Ctrl + 1	Reset the camera to view from the front perspective	
Ctrl + 2	Reset the camera to view from the left perspective	
Ctrl + 3	Reset the camera to view from the right perspective	
Ctrl + 4	Reset the camera to view from the back perspective	
Ctrl + 5	Reset the camera to view from the top perspective	
Ctrl + 6	Reset the camera to view from the bottom perspective	
Ctrl + 7	Reset the camera to view from the isometric perspective	
Ctrl + S	Toggle the structure view type between solid and contour slice	
Aperture Editing		
Key	Description	
Ctrl + Z	Undo the last edit (only tracks edits to undo while in the same instance of the task)	
ESC	Stop drawing manual edits (during line drawing)	

From:

http://apps.dotdecimal.com/ - decimal App Documentation

Permanent link:

http://apps.dotdecimal.com/doku.php?id=electronrt:userguide:keyboard\_controls&rev=1602604461

Last update: 2021/07/29 18:22

