decimal eRT Keyboard & Mouse Controls

The following document details the shortcut keys provided in the user interface of the decimal eRT app. The shortcuts are detailed in their appropriate section of use.

Mouse Controls

Display Views	
Key	Description
Double Left Click	Reset Zoom (fit to scene display)
Right Click + Drag Up	Zoom in
Right Click + Drag Down	Zoom out
Middle Click + Drag	Pan
Left Click + Drag	Rotate (3D only)

Keyboard Controls

	General		
Key	Description		
[Toggle expansion of left side task menu		
]	Toggle expansion of right side task menu		
Ctrl + =	Increase font size		
Ctrl + +	Increase font size		
Ctrl + -	Decrease font size		
Ctrl + 0	Reset font size to default		
F1	Open the user guide to the appropriate article based on the current block/task		
F5	Manual Forced refresh of application and data		
F11	Toggle full screen view		
	3D Views		
Key	Description		
Ctrl + 1	Reset the camera to view from the front perspective		
Ctrl + 2	Reset the camera to view from the left perspective		
Ctrl + 3	Reset the camera to view from the right perspective		
Ctrl + 4	Reset the camera to view from the back perspective		
Ctrl + 5	Reset the camera to view from the top perspective		
Ctrl + 6	Reset the camera to view from the bottom perspective		
Ctrl + 7	Reset the camera to view from the isometric perspective		
Ctrl + S	Toggle the structure view type between solid and contour slice		
Aperture Editing			
Key	Description		
Ctrl + Z	Undo the last edit (only tracks edits to undo while in the same instance of the task)		

	General
ESC	Stop drawing manual edits (during line drawing)

From:

https://apps.dotdecimal.com/ - decimal App Documentation

Permanent link:

https://apps.dotdecimal.com/doku.php?id=electronrt:userguide:keyboard_controls&rev=1602680461

Last update: 2021/07/29 18:22