decimal eRT Keyboard & Mouse Controls

The following page details the shortcut keys provided in the user interface of the decimal eRT app. The shortcuts are detailed in their appropriate section of use.

Mouse Controls

Display Views	
Кеу	Description
Double Left Click	Reset Zoom (fit to scene display)
Right Click + Drag Up	Zoom in
Right Click + Drag Down	Zoom out
Middle Click + Drag	Pan
Left Click + Drag	Rotate (3D only)

Keyboard Controls

General		
Кеу	Description	
[Toggle expansion of left side task menu	
]	Toggle expansion of right side task menu	
Ctrl + =	Increase font size	
Ctrl + +	Increase font size	
Ctrl + -	Decrease font size	
Ctrl + 0	Reset font size to default	
F1	Open the user guide to the appropriate article based on the current block/task	
F5	Manual Forced refresh of application and data	
F11	Toggle full screen view	
3D Views		
Кеу	Description	
Ctrl + 1	Reset the camera to view from the front perspective	
Ctrl + 2	Reset the camera to view from the left perspective	
Ctrl + 3	Reset the camera to view from the right perspective	
Ctrl + 4	Reset the camera to view from the back perspective	
Ctrl + 5	Reset the camera to view from the top perspective	
Ctrl + 6	Reset the camera to view from the bottom perspective	
Ctrl + 7	Reset the camera to view from the isometric perspective	
Ctrl + S	Toggle the structure view type between solid and contour slice	
Aperture Editing		
Кеу	Description	
	Undo the last edit (only tracks edits to undo while in the same instance of the task)	

General

ESC Stop drawing manual edits (during line drawing)

From:

http://apps.dotdecimal.com/ - decimal App Documentation

Permanent link: http://apps.dotdecimal.com/doku.php?id=electronrt:userguide:keyboard_controls&rev=1627583038

Last update: 2021/07/29 18:23

